

1.
5013

CLAPTON COMMON E5

(East Side)

No 98

TQ 3487 8/114
II

2.
Early-mid C19 3-bay villa of 2 storeys and attic. Large proportions. Stock brick with stucco frieze, cornice and blocking course. Slated mansard with 3 dormer windows, the outer ones tripartite. Tall end walls have stucco coping. Stuccoed ground floor to 1st floor band. 1st floor sash windows under gauged brick arches. Ground floor long casements in moulded architraves with detached cornices. Central Doric porch in antis. Modern glazed door. Graded partly for important situation overlooking common.