

1.
5013

CLARENCE PLACE E5
(North Side)

Nos 1 to 7 (consec)

TQ 3485 19/131
II

GV

2.
Early C19 terrace, each 3 storeys and basement, 2 windows. Stock brick with stone -
coped parapet. The upper parts of Nos 3 and 4 have been rebuilt, presumably after war
damage. Gauged flat brick arches to 2nd floor sash windows, some with glazing
bars: and to long casements with transoms and small cast iron balconies on 1st
floor. 1st floor cill band. Ground floor round-headed windows, in round-arched
recesses of gauged brick, some boarded up, some with glazing bars. No 4 has interlaced
bars and margin lights. 6-panel doors with fluted pilasters, cornice head and
wide fanlight with interlaced glazing bars and margin lights. 5 steps with cast
iron handrails. Nos 1 and 2 are empty and decaying. No 7 has 1st floor cast iron
covered balcony.

Nos 1 to 8 (consec) form a group with Nos 20 to 25 (consec) Clapton Square .