

1.  
5013

STOKE NEWINGTON

CHURCH STREET N16  
(South Side)

-----  
Nos 207 to 223 (odd)  
(Park Crescent)

TQ 3286 11/626

II

GV

2.  
Early-mid C19 crescent, each house 3 storeys, attic and basement, 2 windows. Stock brick with stucco frieze, cornice and parapet (some parapets pierced). Banded rusticated stucco ground floor and stuccoed basement. Moulded window architraves, those on 2nd floor with ears and feet and bracketed cills, those on 1st floor with cornices on console brackets. 2nd floor sash windows with glazing bars. 1st floor long casements opening to continuous cast iron balcony stepped out above prostyle Doric porches. Ground floor windows sashes with cast iron guards. 7 steps, with cast iron handrails, to half glazed 4-panel doors.